

Ellon Asset Condition Assessment

Final Report

16 April 2018

www.jbaconsulting.com

JBA Project Manager

Caroline Anderton BSc MSc CEnv CSci MCIWEM C.WEM
Unit 2.1, Quantum Court
Research Avenue South
Heriot Watt Research Park
Riccarton
Edinburgh
EH14 4AP

Revision history

Revision Ref/Date	Amendments	Issued to
S3-P01 / 7 March 2018	Draft Report	Alistair Scotland and Lee Watson, Aberdeenshire Council
S3-P02 / 16 April 2018	Final Report	Alistair Scotland and Lee Watson, Aberdeenshire Council
A1-C01 / 03 April 2019	Published	Alistair Scotland and Lee Watson, Aberdeenshire Council

Contract

This report describes work commissioned by Gavin Penman, on behalf of Aberdeenshire Council, on 10 October 2017 by Purchase Order 1095192. Dougall Baillie's representative for the contract was Scott MacPhail and Aberdeenshire Council's representative for the contract was Alistair Scotland. Christina Kampanou and Stephen Farrar of JBA Consulting carried out this work.

Prepared by Christina Kampanou BSc MEng MSc
Assistant Engineer

Reviewed by Stephen Farrar MEng CEng MICE
Senior Engineer

Purpose

This document has been prepared as a Final Report for Aberdeenshire Council. JBA Consulting accepts no responsibility or liability for any use that is made of this document other than by the Client for the purposes for which it was originally commissioned and prepared.

JBA Consulting has no liability regarding the use of this report except to Aberdeenshire Council.

Copyright

© Jeremy Benn Associates Limited 2018.

Carbon footprint

A printed copy of the main text in this document will result in a carbon footprint of 58g if 100% post-consumer recycled paper is used and 73g if primary-source paper is used. These figures assume the report is printed in black and white on A4 paper and in duplex.

JBA is aiming to reduce its per capita carbon emissions.

Executive summary

An Asset Survey of structures that could influence flood risk has been undertaken along the Ythan, Modley Burn, Broomies Burn, Fortree Burn and Hillhead Burn in Ellon. The visual survey locates their position, identifies their general condition, maintenance required, and if appropriate 'quick wins' that could be undertaken to reduce flood risk.

Properties with property level flood protection measures have been identified from an external visual survey.

Contents

1	Introduction	1
2	River Ythan	2
3	Modley Burn	14
4	Broomies Burn	31
5	Fortree Burn	45
6	Hillhead Burn	48
7	Property Level Protection (PLP)	50

List of Tables

Table 2-1: List of structural assets shown in Figure 2-1	2
Table 2-2: List of structural assets shown in Figure 2-2	3
Table 2-3: List of structural assets shown in Figure 2-3	5
Table 2-4: List of structural assets shown in Figure 2-4	7
Table 2-5: List of structural assets shown in Figure 2-5	10
Table 2-6: List of structural assets shown in Figure 2-6	12
Table 3-1: List of structural assets shown in Figure 3-1	15
Table 3-2: List of structural assets shown in Figure 3-2	16
Table 3-3: List of structural assets shown in Figure 3-3	22
Table 4-1: List of structural assets shown in Figure 4-1	33
Table 4-2: List of structural assets shown in Figure 4-2	34
Table 4-3: List of structural assets shown in Figure 4-3	37
Table 5-1: List of structural assets shown in Figure 5-1	48
Table 6-1: List of structural assets shown in Figure 6-1	52

List of Figures

Figure 2-1: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan	2
Figure 2-2: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan	3
Figure 2-3: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan	6
Figure 2-4: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan	9
Figure 2-5: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan	10
Figure 2-6: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan	12
Figure 3-1: Plan showing the distribution of features identified in the asset condition assessment along the Modley Burn	14
Figure 3-2: Plan showing the distribution of features identified in the asset condition assessment along the Modley Burn	20
Figure 3-3: Plan showing the distribution of features identified in the asset condition assessment along the Modley Burn	25
Figure 4-1: Plan showing the distribution of features identified in the asset condition assessment along the Broomies Burn	31
Figure 4-2: Plan showing the distribution of features identified in the asset condition assessment along the Broomies Burn	34
Figure 4-3: Plan showing the distribution of features identified in the asset condition assessment along the Broomies Burn	37
Figure 4-4: Plan showing the distribution of features identified in the asset condition assessment along the Broomies Burn	40
Figure 5-1: Plan showing the distribution of features identified in the asset condition assessment along the Fortree Burn	45
Figure 6-1: Plan showing the distribution of features identified in the asset condition assessment along the Hillhead Burn	48
Figure 7-1: Plan showing the residential properties with PLP and their house numbers	50
Figure 7-2: Property Level Protection of Cedar Lodge at the Meadows	51
Figure 7-3: Property Level Protection of 5 the Meadows	51
Figure 7-4: Property Level Protection of 6 the Meadows	52
Figure 7-5: Property Level Protection of 8 the Meadows	52
Figure 7-6: Property Level Protection of 9 the Meadows	53
Figure 7-7: Property Level Protection of 11 the Meadows	53
Figure 7-8: Property Level Protection of 13 the Meadows	54

Abbreviations

FPS	Flood Protection Scheme
Approx.	Approximately

1 Introduction

A full walkover survey was undertaken to assess the condition of structures in Ellon in Aberdeenshire as part of the Ellon Flood Protection Study. More specifically, the walkover was undertaken in Ellon along the River Ythan, Modley Burn, Broomies Burn, Fortree Burn and Hillhead Burn. The asset condition assessment has been carried out in accordance with the Environment Agency's Condition Assessment Manual March 2012. Where information provided by the client indicates the risk of blockage is high, or where this is thought to be high this has been recorded. (no formal risk assessment/modelling has been carried out at this stage).

Category	Comments
Date of inspection(s)	28-29 November 2017
Inspector(s)	Stephen Farrar and Christina Kampanou
General inspection information	Weather at the time of the inspection was wet and relatively windy.
Scheme information	The asset survey is on behalf of Aberdeenshire Council.
Nature of inspection(s)	The inspections were walkover surveys of the structural assets in the towns, as well as logging of any PLP within the survey lines. Photographs were taken but no topographic survey work was carried out.
Nature of assets	Culverts and bridges are the main structural assets in Ellon. There are also retaining walls and outlet structures.
General condition / comments	The assets were generally found to be in good condition.

2 River Ythan

Assets are listed below from upstream to downstream, with the numbering referenced in Figure 2-1, Figure 2-2, Figure 2-3, Figure 2-4, Figure 2-5 and Figure 2-6.




Figure 2-1: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan

Table 2-1 – List of structural assets shown in Figure 2-1

Number	Asset	Location
1	Bridge of Ardlethen	B9005

1- Bridge of Ardlethen B9005 (Refer to Figure 2-1)



View from upstream

Type: Three-arched vehicular bridge
Upstream grid ref: NJ 92489 30834
Span (m): 36.9
Material: Masonry
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Minor cracks.
 Some loss of mortar.
 No sign of deformation of arches.
 Potentially high risk of scour.
Risk of Blockage: Low
Maintenance: None Required
Quick Win: N/A




Figure 2-2: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan

Table 2-2 – List of structural assets shown in Figure 2-2

Number	Asset	Location
2	Meiklemill Railway Bridge	Meiklemill
3	Meiklemill Culvert (Outfall)	Meiklemill
4	Meiklemill Culvert Footbridge	Meiklemill

2- Meiklemill Railway Bridge (Refer to Figure 2-2)



View of bridge from downstream

Type: Four-arched bridge
Upstream grid ref: NJ 94713 30323
Span (m): Unknown
Material: Masonry
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 No sign of deformation of arches.
 Minor mortar loss.
 Rust in arch soffits.
 Erosion of right bank.
Risk of Blockage: Low
Maintenance: None Required
Quick Win: N/A



Downstream view



Upstream view

3- Meiklemill Culvert Outlet (Refer to Figure 2-2)



View from downstream

Type: Outfall
Upstream grid ref: NJ 94909 30240
Width (m): Unknown
Material: Concrete
Condition: Grade 3 (Fair)
Part of FPS: Yes
Comments:
 Trash screen connection to culvert compromised by loss of fixings.
 Minor bank erosion downstream.
Risk of Blockage: Moderate
Maintenance: Keep free of debris
Quick Win: Remove trash screen

4- Meikle Mill Footbridge (Refer to Figure 2-2)



View of bridge from downstream

Type: Glulam timber bridge
Upstream grid ref: NJ 95076 30270
Span (m): 55
Material: Timber beam and deck
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Signs of minor deterioration.
 Erosion at both banks.
Risk of Blockage: Low
Maintenance: None Required
Quick Win: N/A



Downstream view



Upstream view




Figure 2-3: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan

Table 2-3 – List of structural assets shown in Figure 2-3

Number	Asset	Location
5	Ellon bridge	A920 (South Road)
6	Old Bridge of Ellon (Footbridge)	Market Street

5- Ellon Bridge A920 (Refer to Figure 2-3)



View of bridge from upstream

Type: Three-arched vehicular bridge
Upstream grid ref: NJ 95681 30315
Span (m): 54.6
Material: Reinforced concrete
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Minor cracks.
 Slight sealant loss.
 No sign of deformation of arches.
 Abutments well founded.
 Minor erosion of banks.
 Potentially at high risk of scour.
Risk of Blockage: Low
Maintenance: None Required
Quick Win: N/A



View of Ellon Bridge from downstream



Upstream view of River Ythan

6- Old Bridge of Ellon (Refer to Figure 2-3)



Upstream view of bridge

Type: Three-arched bridge
Upstream grid ref: NJ 95685 30334
Span (m): 45.8
Material: Masonry
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Lengthy cracks.
 Loss of mortar.
 Water stains.
 Bridge not open to vehicles.
 Increased potential flood risk upstream due to close proximity of two structures.
 Potentially at high risk of scour.
Risk of Blockage: Low
Maintenance: None Required
Quick Win: N/A



View from downstream



View of bridge




Figure 2-4: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan

Table 2-4 – List of structural assets shown in Figure 2-4

Number	Asset	Location
7	Boatie Tam's Brig (Footbridge)	Meadows Way

7- Boatie Tam's Brig (Refer to Figure 2-4)



View of bridge from upstream

Type: Pedestrian bridge
Upstream grid ref: NJ 96666 30364
Span (m): 127.5
Material: Steel beam / metal deck / concrete abutments
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Minor cracks on abutments.
 No sign of deformation of beams.
 Localised surface corrosion.
Risk of Blockage: Low
Maintenance: None Required
Quick Win: N/A




Figure 2-5: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan

Table 2-5 – List of structural assets shown in Figure 2-5

Number	Asset	Location
8	River Ythan Bridge	A90 Road

8- River Ythan Bridge A90 (Refer to Figure 2-5)



View of bridge from upstream

Type: Vehicular bridge
Upstream grid ref: NJ 97460 30304
Span (m): Unknown
Material: Steel beam / concrete columns
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 No sign of deformation of beams. Minor rust.
Risk of Blockage: Low
Maintenance: None Required
Quick Win: N/A



Bridge deck, view from upstream right hand bank



View from underneath from right hand bank




Figure 2-6: Plan showing the distribution of features identified in the asset condition assessment along the River Ythan

Table 2-6: List of structural assets shown in Figure 2-6

Number	Asset	Location
9	Logie Buchan Memorial Bridge	Kirkton of Logie Buchan

9- Logie Buchan Memorial Bridge (Refer to Figure 2-6)



View of bridge from upstream

Type: Nine-span pedestrian bridge
Upstream grid ref: NJ 99078 29927
Span (m): Unknown
Material: Reinforced concrete beam and slab
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Minor cracks and spalling of slab and beam.
 Minor cracks of piers.
 Erosion of left bank.
Risk of Blockage: Low
Maintenance: None Required
Quick Win: N/A



View of bridge



Downstream view of River Ythan from bridge

3 Modley Burn

Assets are listed below from upstream to downstream, with numbering referenced in Figure 3-1, Figure 3-2 and Figure 3-3.




Figure 3-1: Plan showing the distribution of features identified in the asset condition assessment along the Modley Burn

Table 3-2: List of structural assets shown in Figure 3-1

Number	Asset	Location
10	Culvert	Auchterellon Farm
11	Culvert	Golf Course
12	Culvert	Golf Course
13	Culvert	Golf Course
14	Culvert	Golf Course
15	Footbridge	Golf Course
16	Footbridge	Golf Course

Table 3-2: List of structural assets shown in Figure 3-1

17	Footbridge	Golf Corse
18	Hospital Road Culvert (inlet)	Golf Course

10 - Simple culvert (Refer to Figure 3-1)



View from downstream of culvert


Type: Simple culvert
Upstream grid ref: NJ 94676 31743
Width (m): Unknown
Length (m): 2.5 approx.
Material: Masonry
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Culvert at side, masonry arch brick.
 Steep bank.
 Heavily vegetated channel.
Risk of Blockage: Moderate
Maintenance: Keep free of debris, keep vegetation growth under control.
Quick Win: N/A


11 - Culvert (Refer to Figure 3-1)



View from upstream of culvert

Type: Simple culvert
Upstream grid ref: NJ 94956 31506
Material: Stone
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Simple culvert at golf course.
 Minor erosion at bank sides.
 No signs of sediment deposition.
Risk of Blockage: Moderate
Maintenance: Keep free of debris
Quick Win: N/A

12 - Culvert (Refer to Figure 3-1)	
 <p><i>View from upstream of culvert</i></p>	<p>Type: Simple culvert Upstream grid ref: NJ 94977 31490 Material: Stone Condition: Grade 2 (Good) Part of FPS: No Comments: Pipe upstream of the culvert. Stable bank. Risk of Blockage: Moderate Maintenance: Keep free of debris Quick Win: N/A</p>

13 - Culvert (Refer to Figure 3-1)	
 <p><i>View from upstream of culvert</i></p>	<p>Type: Simple culvert Upstream grid ref: NJ 95018 31458 Material: Stone Condition: Grade 2 (Good) Part of FPS: No Comments: None Risk of Blockage: Moderate Maintenance: Keep free of debris Quick Win: N/A</p>

14 - Culvert (Refer to Figure 3-1)



View from upstream of culvert

Type: Simple culvert
Upstream grid ref: NJ 95071 31439
Material: Stone
Condition: Grade 2 (Good)
Part of FPS: No
Comments: None
Risk of Blockage: Moderate
Maintenance: Keep free of debris
Quick Win: N/A

15 - Footbridge (Refer to Figure 3-1)



View from upstream of footbridge

Type: Single-span footbridge
Upstream grid ref: NJ 95112 31396
Width (m): 1 (approximately)
Material: Steel
Condition: Grade 2 (Good)
Part of FPS: No
Comments: Eroded left bank directly upstream of the bridge.
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A

16 - Steel footbridge (Refer to Figure 3-1)



View from downstream of footbridge

Type: Bridge
Upstream grid ref: NJ 95121 31370
Material: Steel / stone
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Steel / concrete deck.
 Open-jointed stone abutment.
 Erosion of left bank.
 Bridge deck flooded.
Risk of Blockage: Moderate
Maintenance: Keep free of debris
Quick Win: N/A

17 - Timber footbridge (Refer to Figure 3-1)



View from upstream of footbridge

Type: Timber footbridge
Upstream grid ref: NJ 95110 31307
Material: Timber
Width (m): 1 approx.
Condition: Grade 5 (Very Poor)
Part of FPS: No
Comments:
 Timber slippery and showing signs of rot.
 Supports showing signs of settlement.
 Small amounts of sediment deposited.
Risk of Blockage: Moderate
Maintenance: Keep free of debris
Quick Win: N/A

18 – Hospital Road Culvert Inlet (Refer to Figure 3-1)



View from upstream of culvert

Type: Simple culvert
Upstream grid ref: NJ 95115 31300
Material: Concrete
Length (m): 245 approx.
Condition: Grade 3 (Fair)
Part of FPS: Yes
Comments:
 Significant amount of undercutting along left and right bank.
 Ivy on left hand side.
 Sediment deposition.
 Trash screen detached.
 Brickwork element.
 Open masonry joints.
 Minor cracks.
 Service pipe inside culvert.
Risk of Blockage: High
Maintenance: Keep watercourse free of debris
Quick Win: Remove debris, remove detached trash screen



Trash screen and debris in river



View from upstream of culvert. Service pipe inside culvert




Figure 3-2: Plan showing the distribution of features identified in the asset condition assessment along the Modley Burn

Table 3-2: List of structural assets shown in Figure 3-2

Number	Asset	Location
19	Hospital Road Culvert (Outlet)	Hospital Road
20	Culvert	Hospital Road
21	Culvert	Hospital Road
22	Station Road Culvert	B9005

19 - Hospital Road Culvert Outlet (Refer to Figure 3-2)



View from downstream of culvert

Type: Masonry arch brick culvert

Upstream grid ref: NJ 95041
31076

Span (m): 2.49

Material: Masonry

Condition: Grade 3 (Fair)

Part of FPS: Yes

Comments:

Minor cracks.

Mortar loss.

Minor vegetation growth between blocks.

Heavily vegetated banks.

Risk of Blockage: Moderate

Maintenance: Keep free of debris




Quick Win: N/A



Downstream end of culvert



Downstream view of watercourse

20 – Culvert (Refer to Figure 3-2)	
	<p>Type: Simple culvert Upstream grid ref: NJ 95056 30922 Height (m): 1.5 Width (m): 1.825 Length (m): 3 approx. Material: Masonry Condition: Grade 2 (Good) Part of FPS: Yes Comments: Minor settlement of culvert. No vegetation through culvert walls. Minor mortar loss. Steep and slightly eroded banks at upstream side of culvert. Tree supporting right bank at upstream side of culvert. Steep and unvegetated right bank at downstream side of culvert. Severe erosion of left hand bank downstream. Risk of Blockage: Low Maintenance: Keep free of debris Quick Win: N/A</p>
	
<p><i>Upstream view of watercourse</i></p>	<p><i>View from downstream of culvert showing eroded banks (outlet)</i></p>

21 - Retaining wall (Refer to Figure 3-2)



Upstream view of wall

Type: Retaining wall
Upstream grid ref: NJ 95052 30762
Height (m): 1.5
Length (m): 19 approx.
Material: Concrete
Condition: Grade 3 (Fair)
Part of FPS: Yes
Comments:
 Minor cracking.
 Sealant seepage through joints.
 Minor vegetation growth.
 Outfall next to wall at upstream.
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A



View from downstream of the wall showing water stains




Outfall next to the upstream side of the wall

22 - Station Road Culvert B9005 (Refer to Figure 3-2)



Upstream view of culvert

Type: Simple culvert
Upstream grid ref: NJ 95060 30627
Width (m): 2.185
Length (m): 3 approx.
Material: Masonry
Condition: Grade 2 (Good)
Part of FPS: Yes
Comments:
 No sign of movement.
 Open joints in masonry wall upstream.
 Overgrown and undercut banks downstream.
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A



Upstream view of watercourse



Downstream end of culvert




Figure 3-3: Plan showing the distribution of features identified in the asset condition assessment along the Modley Burn

Table 3-3: List of structural assets shown in Figure 3-3

Number	Asset	Location
23	Modley Burn Bridge	Modley Place
24	Ellon Primary School Bridge	Modley Place
25	Footbridge	Modley Place
26	Masonry Wall	Modley Place
27	Gabion Baskets	Modley Place
28	Gordon Park Footbridge	Gordon Park
29	Footbridge	Gordon Park

23 - Modley Burn Bridge (Refer to Figure 3-3)



Upstream view of culvert

Type: Simple arch culvert
Upstream grid ref: NJ 95074 30565
Span (m): 3.5
Length (m): 7.3
Width (between walls) (m): 5.335
Material: Reinforced concrete
Condition: Grade 3 (Fair)
Part of FPS: Yes
Comments:
 Cracking in render.
 Sealant loss.
 Seepage through joints.
 Minor crest lowering.
 Eroded and overgrown banks.
Risk of Blockage: Moderate
Maintenance: Keep free of debris
Quick Win: N/A



Modley Burn bridge



Downstream end of culvert

24- Ellon Primary School footbridge (Refer to Figure 3-3)



Downstream view of footbridge

Type: Arch footbridge
Upstream grid ref: NJ 95071 30520
Material: Concrete deck and abutments / steel parapet
Length (m): 1 approx.
Condition: Grade 2 (Good)
Part of FPS: Yes
Comments:
 Minor cracks at abutments.
 No deformation to arch.
 Superficial defects.
 Eroded banks upstream and downstream.
 Weir effect over invert.
Risk of Blockage: Moderate
Maintenance: Keep channel free of debris
Quick Win: N/A

25- Footbridge (Refer to Figure 3-3)



Upstream view of footbridge

Type: Single-span footbridge
Upstream grid ref: NJ 95078 30453
Length (m): 2.8
Material: Concrete / steel parapet
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Minor cracks in deck.
 Severe corrosion of handrails.
 Deformation of rails.
 Pipe directly downstream of the bridge.
 Heavily vegetated banks upstream and downstream.
Risk of Blockage: Moderate
Maintenance: Remove any debris and control vegetation growth
Quick Win: N/A

25- Footbridge (Refer to Figure 3-3)



Downstream view of watercourse



View of bridge

26- Masonry Wall (Refer to Figure 3-3)



Downstream view

Type: Masonry Wall
Upstream grid ref: NJ 95074 30452
Material: Masonry
Condition: Grade 5 (Very Poor)
Part of FPS: No
Comments:
 Major masonry loss.
 Loss of backfill / ground behind the wall.
Risk of Blockage: Low
Maintenance: Maintain channel free of debris
Quick Win: N/A

27- Gabion Baskets (Refer to Figure 3-3)



Upstream view

Type: Gabions
Upstream grid ref: NJ 95074 30452
Material: Masonry
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Some distortion of alignment.
 Minor evidence of sliding.
 Packed below maximum capacity.
 Poor maintenance access.
Risk of Blockage: Low
Maintenance: Maintain channel free of debris
Quick Win: N/A

28- Gordon Park footbridge (Refer to Figure 3-3)



View of footbridge

Type: Single-span footbridge
Upstream grid ref: NJ 95081 30356
Length (m): 1.8
Material: Concrete deck / masonry abutments / timber parapet / additional steel angles to parapet
Condition: Grade 3 (Fair)
Part of FPS: Yes
Comments:
 Timber fence showing signs of rot.
 Slight block displacement.
 Possible minor lateral movement at base of abutments.
 Pipe directly upstream of bridge.
Risk of Blockage: High
Maintenance: Keep channel free of debris
Quick Win: N/A

28- Gordon Park footbridge (Refer to Figure 3-3)



View from upstream



View from downstream

29- Footbridge (Refer to Figure 3-3)



View of footbridge

Type: Single-span footbridge
Upstream grid ref: NJ 95076
30330

Material: Steel / masonry
abutments / timber decking

Condition: Grade 3 (Fair)

Part of FPS: Yes

Comments:

Signs of deformation.

Minor corrosion.

Decking worn.

Open-jointed stonework.

Risk of Blockage: Moderate

Maintenance: Keep free of debris

Quick Win: N/A

4 Broomies Burn

Assets are listed below from upstream to downstream, with numbering referenced in Table 4-1 and Figure 4-1, Figure 4-2, Figure 4-3 and Figure 4-4.




Figure 4-1: Plan showing the distribution of features identified in the asset condition assessment along the Broomies Burn

Table 4-1: List of structural assets shown in Figure 4-1

Number	Asset	Location
30	Broomfield Bridge	Unnamed Road
31	Bridge	Unnamed Road

30- Broomfield bridge (Refer to Figure 4-1)



View of culvert from upstream

Type: Masonry slab culvert
Upstream grid ref: NJ 96150 32320

Span (m): 0.79

Length (m): 2.5 approx.

Material: Masonry

Condition: Grade 3 (Fair)

Part of FPS: No

Comments:

Root penetration through culvert.

Loss of mortar at joints.

Thickly vegetated banks.

Poor access.

Debris in watercourse downstream.

Scour pool downstream.

Risk of Blockage: High

Maintenance: Keep vegetation growth under control, remove debris

Quick Win: Cut trees around culvert, remove debris and collapsed fence.



View of culvert from downstream



Downstream view of watercourse

31- Bridge (Refer to Figure 4-1)	
 <p><i>Downstream view of culvert</i></p>	<p>Type: Circular culvert Upstream grid ref: NJ 96417 31918 Span (m): 1.2 Length (m): 2 approx. Material: Pre-cast concrete Condition: Grade 3 (Fair) Part of FPS: No Comments: Small scour pool downstream. Severely eroded and heavily vegetated banks. Culvert invert buried deep into bed. Small opening size. Risk of Blockage: High Maintenance: Keep culvert clean and remove debris Quick Win: N/A</p>
 <p><i>Upstream view of watercourse</i></p>	 <p><i>Downstream view of watercourse</i></p>




Figure 4-2: Plan showing the distribution of features identified in the asset condition assessment along the Broomies Burn

Table 4-2: List of structural assets shown in Figure 4-2

Number	Asset	Location
32	Masonry Culvert	Unnamed Road
33	Broomies Bridge A948	A948 Road
34	Timber Bridge	Balmacassie Community Woodland

32- Masonry culvert (Refer to Figure 4-2)



Upstream view of culvert

Type: Masonry culvert and headwall
Upstream grid ref: NJ 96531 31663
Span (m): Unknown
Material: Masonry
Length (m): 12
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Minor loss of mortar and spalling of arch and headwalls.
 High risk of scour (according to Aberdeenshire Council's notes).
Risk of Blockage: Low
Maintenance: Keep free of debris
Quick Win: N/A

33- Broomies Bridge A948 (Refer to Figure 4-2)



Downstream view of culvert

Type: Box culvert
Upstream grid ref: NJ 96554 31481
Span (m): 2
Rise (m): 0.8
Length (m): 7.3
Material: Reinforced concrete
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Minor superficial defects.
 Heavily vegetated banks.
Risk of Blockage: High
Maintenance: Keep growth of vegetation under control, keep free of debris
Quick Win: Remove vegetation around culvert's entrance/exit

34- Timber bridge (Refer to Figure 4-2)



Upstream view of bridge

Type: Pedestrian bridge
Upstream grid ref: NJ 96621 31227
Span (m): 3
Width (m): 2
Material: Timber
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Minor deformation of beam.
 Rotten and distorted handrails.
 Minor splits of timber decking.
 Fixings present.
Risk of Blockage: Moderate
Maintenance: Keep vegetation growth under control
Quick Win: N/A



View of bridge from upstream



Downstream view of watercourse










Figure 4-3: Plan showing the distribution of features identified in the asset condition assessment along the Broomies Burn


Table 4-3: List of structural assets shown in Figure 4-3

Number	Asset	Location
35	Footbridge	Balmacassie Community Woodland
36	Culvert	Balmacassie Way
37	Culvert A920	A920 (Castle Road)

35- Footbridge (Refer to Figure 4-3)	
 <p>View of bridge</p>	<p>Type: Pedestrian bridge Upstream grid ref: NJ 96666 31155 Span (m): 4 Width (m): 1.9 Height (m): 1.5 (approximately) Material: Timber Condition: Grade 3 (Fair) Part of FPS: No Comments: Erosion at abutments. Slightly distorted and rotten handrails. Minor splits of timber decking. Minor vegetation growth on deck. Exposed loose fixings, washers missing. Risk of Blockage: Moderate Maintenance: Keep vegetation growth under control Quick Win: N/A</p>
 <p>Upstream view of bridge</p>	 <p>Downstream view of bridge, loose fixings</p>

36- Culvert (Refer to Figure 4-3)	
 <p>Upstream view of culvert</p>	<p>Type: Semi-circular culvert Upstream grid ref: NJ 96688 31109 Width (m): 3.6 Length (m): 17 approx. Material: Corrugated steel / concrete Condition: Grade 2 (Good) Part of FPS: No Comments: Vegetation growth on top of culvert. Heavily vegetated banks.</p>

36- Culvert (Refer to Figure 4-3)	
	<p>Concrete outlet structure present directly upstream.</p> <p>Risk of Blockage: Moderate</p> <p>Maintenance: Keep watercourse free of debris</p> <p>Quick Win: N/A</p>
 <p><i>Concrete outlet structure next to culvert</i></p>	 <p><i>Upstream view of watercourse</i></p>

37- Culvert A920 (Refer to Figure 4-3)	
 <p><i>Upstream view of culvert</i></p>	<p>Type: Simple culvert, hollow concrete slab</p> <p>Upstream grid ref: NJ 96955 30653</p> <p>Inlet span (m): 3.1</p> <p>Outlet span (m): 2.8</p> <p>Rise (m): 0.6</p> <p>Length (m): 33</p> <p>Material: Reinforced concrete slab and abutment</p> <p>Condition: Grade 2 (Good)</p> <p>Part of FPS: No</p> <p>Comments: Minor settlement of soffit. Minor vegetation growth on soffit. Concrete outlet structure directly upstream.</p> <p>Risk of Blockage: High</p> <p>Maintenance: Keep culvert and trash screen free of debris</p> <p>Quick Win: Remove excess vegetation, remove trash screen</p>

37- Culvert A920 (Refer to Figure 4-3)



Concrete outlet structure



Downstream end of culvert




Figure 4-4: Plan showing the distribution of features identified in the asset condition assessment along the Broomies Burn

Table 4-4: List of structural assets shown in Figure 4-4

Number	Asset	Location
38	Footbridge	The Meadows
39	Culvert	The Meadows
40	Footbridge	The Meadows
41	Culvert	The Meadows
42	Footbridge	The Meadows
43	Culvert	The Meadows

38- Footbridge (Refer to Figure 4-4)



View of bridge



Type: Footbridge
Upstream grid ref: NJ 97085 30578
Width (m): 3.6
Material: Timber / masonry
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Superficial defects on handrails.
 Steps in channel downstream.
 Watercourse channelized upstream and downstream.
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A



Watercourse downstream



Watercourse upstream

39- Culvert (Refer to Figure 4-4)	
 <p><i>Upstream view of culvert</i></p>	<p>Type: Simple culvert Upstream grid ref: NJ 97099 30561 Width (m): 1 Material: Masonry Condition: Grade 1 (Very Good) Part of FPS: No Comments: No cracks. No distortion of shape. Risk of Blockage: Moderate Maintenance: Keep free of debris Quick Win: N/A</p>
40- Footbridge (Refer to Figure 4-4)	
 <p><i>Downstream view of bridge</i></p>	<p>Type: Single-span footbridge Upstream grid ref: NJ 97127 30536 Material: Timber Condition: Grade 1 (Very Good) Part of FPS: No Comments: No visible defects. No signs of deterioration of timber or fixings. Bridge ties into wall. Risk of Blockage: Low Maintenance: None required Quick Win: N/A</p>

41- Culvert (Refer to Figure 4-4)



Upstream view of culvert




Type: Twin-bore stone culvert
Upstream grid ref: NJ 97135 30527
Material: Timber
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Loose stonework over top of culvert.
 Minor vegetation growth.
 Displaced stonework.
Risk of Blockage: High
Maintenance: Keep free of debris
Quick Win: N/A

42- Footbridge (Refer to Figure 4-4)



Upstream view of footbridge

Type: Single-span footbridge
Upstream grid ref: NJ 97134 30523
Material: Timber
Condition: Grade 1 (Very Good)
Part of FPS: No
Comments:
 No visible defects.
 No signs of deterioration of timber or fixings.
Risk of Blockage: Moderate
Maintenance: Keep free of debris
Quick Win: N/A

43- Culvert (Refer to Figure 4-4)	
 <p><i>Upstream view of culvert</i></p>	<p>Type: Twin-bore stone culvert Upstream grid ref: NJ 97148 30505 Material: Stone Condition: Grade 4 (Poor) Part of FPS: No Comments: Possible deformation of shape. Possible displacement of stonework at downstream end. Risk of Blockage: High Maintenance: Keep free of debris Quick Win: N/A</p>
 <p><i>Downstream end of culvert</i></p>	 <p><i>Downstream view of watercourse</i></p>

5 Fortree Burn

Assets are listed below from upstream to downstream with numbering referenced in Table 5-1 and Figure 5-1.




Figure 5-1: Plan showing the distribution of features identified in the asset condition assessment along the Fortree Burn

Table 5-1: List of structural assets shown in Figure 5-1

Number	Asset	Location
44	Culvert	Meiklemill
45	Stone Culvert	Meiklemill
46	Meiklemill Culvert	Golf Course

44- Stone culvert (Refer to Figure 5-1)



Culvert upstream

Type: Twin-bore culvert
Upstream grid ref: NJ 94870 29581
Height (m): 0.5
Width of right bore (m): 0.6
Width of left bore (m): 0.5
Diameter (m): 0.45
Pipe Cover (m): 0.6
Material: Stone extended with concrete pipe
Condition: Grade 4 (Poor)
Part of FPS: No
Comments:
 Vegetation growth between stonework.
 Minor deformation of bores.
 Eroded banks upstream and downstream.
 No trash screen.
 Neighbour complaining that culvert causes flooding (possible collapse).
Risk of Blockage: High
Maintenance: Keep free of debris
Quick Win: N/A



Culvert downstream



Downstream view of watercourse

45- Stone culvert (Refer to Figure 5-1)



View from downstream of culvert

Type: Simple culvert
Upstream grid ref: NJ 94802 29695
Width (m): Unknown
Material: Stone
Condition: Grade 3 (Fair)
Part of FPS: No
Comments: Vegetation blocking part of culvert. Distortion of cross section.
Risk of Blockage: High
Maintenance: Keep vegetation growth under control
Quick Win: N/A



Upstream view



Downstream view

46- Meiklemill culvert (Refer to Figure 5-1)



Upstream view of culvert (inlet)

Type: Semi-circular simple culvert
Upstream grid ref: NJ 94731 29809
Width (m): 1.5 (approximately)
Diameter (m): 0.75 (approximately)
Material: Concrete
Condition: Grade 4 (Poor)
Part of FPS: No
Comments: Minor cracks and spalling. Minor settlement. Rust staining. High and stiff vegetation at both sides of bank. Distortion of trash screen's bars.

46- Meiklemill culvert (Refer to Figure 5-1)

Timber protective fence partially collapsed.
Risk of Blockage: High
Maintenance: Keep vegetation growth under control
Quick Win: Replace trash screen

6 Hillhead Burn

Assets are listed below from upstream to downstream with numbering referenced in Table 6-1 and Figure 6-1.




Figure 6-1: Plan showing the distribution of features identified in the asset condition assessment along the Hillhead Burn

Table 6-1: List of structural assets shown in Figure 6-1

Number	Asset	Location
47	Hillhead Drive Culvert	Hillhead Drive

47- Hillhead Drive culvert (Refer to Figure 6-1)



Culvert upstream (inlet with trash screen)

Type: Culvert headwall and screen
Upstream grid ref: NJ 95343 29732
Headwall Height (m): 2.1
Headwall Width (m): 2.31
Material: Concrete / masonry
Condition: Grade 3 (Fair)
Part of FPS: Yes
Comments:
 Vertical cracks at corners of old headwall.
 Minor vegetation growth on concrete headwalls.
 Loss of mortar at masonry headwall.
 Moderately steep and eroded banks.
 High flows bypass the culvert.
 Poor access to clean trash screen.
 Not tied in to surrounding ground.
Risk of Blockage: Moderate
Maintenance: Keep trash screens free of debris
Quick Win: Tie in head wall to surrounding ground



Trash screen upstream of culvert



Upstream view of watercourse

7 Property Level Protection (PLP)

Property Level Protection was recorded in residential properties at the bottom of Broomies Burn in the Meadows. Figure 7-1 shows the properties with PLP. The survey only identifies externally visible measures. Internal measures such as watertight doors, non-return valves etc. have not been identified.




Figure 7-1: Plan showing the residential properties with PLP and their house numbers

All properties have used airbrick covers as a measure to mitigate flood risk. Figures 7-2, 7-3, 7-4, 7-5, 7-6, 7-7 and 7-8 show the PLP products used in the Meadows residential properties shown above.



Figure 7-2: Property Level Protection of Cedar Lodge at The Meadows



Figure 7-3: Property Level Protection of 5 The Meadows



Figure 7-4: Property Level Protection of 6 The Meadows



Figure 7-5: Property Level Protection of 8 The Meadows



Figure 7-6: Property Level Protection of 9 The Meadows



Figure 7-7: Property Level Protection of 11 The Meadows



Figure 7-8: Property Level Protection of 13 The Meadows

Appendices

A Complete list of structural assets

A.1 River Ythan

Table A-1 Structural assets along the River Ythan

Number	Asset	Location	Condition
1	Bridge of Ardlethen	B9005	Grade 2
2	Meiklemill Railway Bridge	Meiklemill	Grade 3
3	Meiklemill Culvert (Outfall)	Meiklemill	Grade 3
4	Meiklemill Footbridge	Meiklemill	Grade 2
5	Ellon Bridge A920	A920 (South Road)	Grade 2
6	Old Bridge of Ellon	Market Street	Grade 3
7	Boatie Tam's Brig	Meadows Way	Grade 2
8	River Ythan Bridge	A90	Grade 2
9	Memorial Bridge	Kirkton of Logie Buchan	Grade 2

A.2 Modley Burn

Table A-2 Structural assets along the Modley Burn

Number	Asset	Location	Condition
10	Culvert	Auchterellon Farm	Grade 2
11	Culvert	Golf Course	Grade 2
12	Culvert	Golf Course	Grade 2
13	Culvert	Golf Course	Grade 2
14	Culvert	Golf Course	Grade 2
15	Footbridge	Golf Course	Grade 2
16	Footbridge	Golf Course	Grade 3
17	Footbridge	Golf Course	Grade 5
18	Hospital Road Culvert (Inlet)	Golf Course	Grade 3 High Risk of Blockage
19	Hospital Road Culvert (Outlet)	Hospital Road	Grade 3
20	Culvert	Hospital Road	Grade 2

Table A-2 Structural assets along the Modley Burn

21	Retaining Wall	Hospital Road	Grade 3
22	Station Road Culvert	Station Road B9005	Grade 2
23	Modley Burn bridge	Modley Place	Grade 3
24	Ellon Primary School Bridge	Modley Place	Grade 2
25	Footbridge	Modley Place	Grade 2
26	Masonry Wall	Modley Place	Grade 5
27	Gabion Baskets	Modley Place	Grade 2
28	Gordon Park Footbridge	Gordon Park	Grade 3 High Risk of Blockage
29	Footbridge	Gordon Park	Grade 3

A.3 Broomies Burn

Table A-3 Structural assets along the Broomies Burn

Number	Asset	Location	Condition
30	Broomfield Bridge	Unnamed Road	Grade 3 High Risk of Blockage
31	Bridge	Unnamed Road	Grade 3 High Risk of Blockage
32	Masonry Culvert	Unnamed Road	Grade 2
33	Broomies Bridge A948	A948 Road	Grade 2 High Risk of Blockage
34	Timber Bridge	Balmacassie Community Woodland	Grade 3
35	Footbridge	Balmacassie Community Woodland	Grade 3
36	Culvert	Balmacassie Way	Grade 2
37	Broomies Bridge	A920	Grade 2 High Risk of Blockage
38	Footbridge	The Meadows	Grade 2
39	Culvert	The Meadows	Grade 1
40	Footbridge	The Meadows	Grade 1
41	Culvert	The Meadows	Grade 3 High Risk of Blockage
42	Footbridge	The Meadows	Grade 1
43	Culvert	The Meadows	Grade 4 High Risk of Blockage

A.4 Fortree Burn

Table A-4 Structural assets along the Fortree Burn

Number	Asset	Location	Condition
44	Culvert	Meiklemill	Grade 4 High Risk of Blockage
45	Stone Culvert	Meiklemill	Grade 3 High Risk of Blockage
46	Meiklemill Culvert	Golf Course	Grade 4 High Risk of Blockage

A.5 Hillhead Burn

Table A-5 Structural assets along the Hillhead Burn

Number	Asset	Location	Condition
47	Hillhead Drive Culvert	Hillhead Drive	Grade 3

Offices at

Coleshill
Doncaster
Dublin
Edinburgh
Exeter
Glasgow
Haywards Heath
Isle of Man
Limerick
Newcastle upon Tyne
Newport
Peterborough
Saltaire
Skipton
Tadcaster
Thirsk
Wallingford
Warrington

Registered Office

South Barn
Broughton Hall
SKIPTON
North Yorkshire
BD23 3AE
United Kingdom

+44(0)1756 799919
info@jbaconsulting.com
www.jbaconsulting.com
Follow us:  

Jeremy Benn Associates Limited

Registered in England 3246693

JBA Group Ltd is certified to:
ISO 9001:2015
ISO 14001:2015
OHSAS 18001:2007

